ECS Configuration Change Request Page 1 of 1 Pages					
CCR 97-101	Logged	Date 6/26/97	Rev	Request	Type CCR
Priority Routine	X Urgent	Emergency	Affected Release	В	Change Class II
Title (description) Define Release B.0 NSIDC DAAC HW/SW Baseline					
Documents Affected None			Source Nos (RID, NCR, Action Item, GSFC CCR, etc.) or Tech Reference None		
RTM	Start Base	New □ Pline	None		
Problem NSIDC DAAC HW/SW mapping to support B.0 site installation.					
Proposed Solution Review and approve attached files containing: 1. NSIDC DAAC B.0 HW/SW mapping.					
Impact Analysis:					
Organizations Affected:	воо 🔲	Contracts	ECS Chief Eng	FOS	M&O
Procurement Science Off	QO Security	Rel. Dev X Subcontrct	Rel. A Sys. Eng	Rel. C Sys Verf Acpt	SCDO Arch.
Cost:	None X	Small	Medium	Large	
		(Not exceeding \$100,00	0)(\$100,000 to \$500,000)	(Over \$500,0	00)
Schedule:	None	Other			
Additional LOC			Man-Month	ns	_
Materials					
Originator C. Van Steenberg, Const. Ofc. Charleen Vanster			erg		
Const. Of		Signature			Date
Office Rel B Mgr.	_ Office Manager	Mary Armstrong Signature			Date
Disposition	Approved X	Approved w/Comm	nent Forw	ard	Disapproved

CM01OC96 ECS

Date

Ramsey Billups Signature

CCB Chairperson